



Product certificate

ADRIFÖL FS Racing 10W-60

0002-000151

Description

ADRIFÖL FS Racing 10W-60 is a high-alloyed, synthetic, smooth-running, multi-grade engine oil with specially selected base oils. Thanks to its special additives, ADRIFÖL FS Racing 10W-60 is also suitable for an extremely sporting driving style.

ADRIFÖL FS Racing 10W-60 is ideally suited to modern petrol engines under the heaviest of loads during car racing. ADRIFÖL FS Racing 10W-60 ensures an optimal lubrication layer, even at very high operating temperatures.

Instructions for use

ADRIFÖL FS Racing 10W-60 can be used as a special oil for car racing, even under the harshest of conditions.

Quality classification

Specification

- ACEA A3/B4
- API SN/CF

ADRIFÖL FS Racing 10W-60 is tried and tested in practice in aggregates requiring adherence to manufacturer's fluid specifications:

- MB 229.1
- VW 501 00/505 00
- BMW M Series
- FIAT 9.55535-H3

Properties

- Good fuel economy in partial- and full-load operation.
- A very stable and excellent viscosity behaviour and shear stability
- Excellent cold starting properties
- High oil film stability to prevent wear
- Secure lubrication layer, even at very high operating temperatures
- Extensive protection against wear, corrosion and foaming.
- Very good detergent and dispersing properties
- Extended oil change intervals protect natural resources
-

Technical specifications

Properties	Data	Unit	Testing under
kinematic viscosity at 40°C	160,1	MM ² /S	DIN ISO 51562-2
kinematic viscosity at 100°C	23,1	MM ² /S	DIN ISO 51562-2
viscosity index	174		DIN ISO 2909
appearance	YELLOWBROWN		visually
density at 15°C	855	KG/M ³	DIN EN ISO 12185
Pour Point	-39	°C	ASTM D 7346

All declared values are approximate and subject to standard production variations.

To the best of our knowledge all information reflects the current state of findings and our development. Subject to change. Any reference to DIN standards are solely for product description purposes and do not represent a guarantee. If problems arise, please consult a technician.